

# Hurricane Maria wore out and cracked Ash mountain in Guayama <sup>[1]</sup>

Submitted on 27 October 2017 - 9:32am

*This article is reproduced by CienciaPR with permission from the original source.*

**CienciaPR Contribution:** No

**Original Source:** [Dialogo Digital](#) <sup>[2]</sup>

**By:** Jason Rodríguez y Omar Alfonso



Fotos tomadas por La Perla del Sur contradicen declaraciones públicas del presidente de AES, Manuel Mata, quien la pasada semana expresó que el huracán María no tuvo efecto alguno sobre el colosal montículo de cenizas tóxicas de carbón. (Jason Rodríguez/L

The colossal mound of toxic coal ashes that the AES Puerto Rico Company keeps south of its plant in the Jobos neighborhood of Guayama was not immune to the effects of the powerful

hurricane Maria.

As evidenced photographs taken by the Pearl of the South last Friday, September 29, the mountain was eroded because of the rains and winds winds.

For the full article, please refer to the Spanish version of this site.

## Tags:

- [AES](#) <sup>[3]</sup>
- [cenizas](#) <sup>[4]</sup>
- [Guayama](#) <sup>[5]</sup>

Copyright © 2006-Present CienciaPR and CAPRI, except where otherwise indicated, all rights reserved

[Privacy](#) | [Terms](#) | [About CienciaPR](#) | [Contact Us](#)

---

**Source URL:** <https://www.cienciapr.org/en/external-news/hurricane-maria-wore-out-and-cracked-ash-mountain-guayama?language=en>

## Links

[1] <https://www.cienciapr.org/en/external-news/hurricane-maria-wore-out-and-cracked-ash-mountain-guayama?language=en>

[2] <http://dialogoupr.com/huracan-maria-desgasto-y-agrieto-montana-de-cenizas-en-guayama/>

[3] <https://www.cienciapr.org/en/tags/aes?language=en>

[4] <https://www.cienciapr.org/en/tags/cenizas?language=en>

[5] <https://www.cienciapr.org/en/tags/guayama?language=en>